

Safety Alerts					
Download	Date	Subject	Affected	Compliance	Manual
SA-ASTM-CT_01-en	15-10-2008	Engine Mount Bolts	s/n up to 05-05-01 (including)	n/a	n/a
Service Bulletins					
Download	Date	Subject	Affected	Compliance	Manual
SB-ASTM-CT_03	08-10-2010	Garmin SL30 and SL40 Comm Radio Spurious Emissions Correction	Aircraft with Garmin SL30 or SL40 & aircraft production date before AUG 2010 (excluded), or retrofitted with SL 30/40 produced before to OCT 2010 (excluded)	mandatory, w/o time limit	n/a
SB-ASTM-CT_01-en	15-10-2008	Landing Gear Inspection	All s/n	n/a	n/a
SB-ASTM-CT_02-en	15-10-2008	Inspection of Neuform 3-Bladed Variable Pitch Propeller Installation	All aircrafts equipped with Neuform 3-blade Variable Pitch Propeller	before the next flight	n/a
Service Notifications					
Download	Date	Subject	Affected	Compliance	Manual
SN-ASTM-CT_01-en	15-10-2008	Rohacell ® foam core	All s/n	n/a	n/a
SN-ASTM-CT_02-en	15-10-2008	Engine coolant	All s/n	n/a	n/a
SN-ASTM-CT_03-en	15-10-2008	Coolant hose chafing	up to 02-06-04-25 (including)	n/a	n/a
SN-ASTM-CT_04-en	15-10-2008	Upper rudder hinge	All s/n	n/a	n/a
SN-ASTM-CT_05-en	15-10-2008	Aileron Bracket	up to 04-04-01	n/a	n/a
SN-ASTM-CT_06-en	22-09-2008	Information on Usage of Etdanol Blended Fuel	All s/n	n/a	n/a